



- ### LEGEND
- EXISTING DECIDUOUS TREE TO REMAIN
 - EXISTING DECIDUOUS TREE TO BE REMOVED (REFER TO ARBORIST REPORT)
 - EXISTING CONIFEROUS TREE TO REMAIN
 - EXISTING CONIFEROUS TREE TO BE REMOVED (REFER TO ARBORIST REPORT)
 - TREE IDENTIFICATION KEY (TREES TO BE RETAINED)
 - TREE IDENTIFICATION KEY (TREES TO BE REMOVED)
 - TREE IDENTIFICATION KEY (TREES PREVIOUSLY REMOVED)
 - TREE PROTECTION FENCING PER CITY OF BARRIE STANDARDS

- ### GENERAL NOTES
1. Do not scale the drawings. All dimensions are in millimetres unless noted otherwise.
 2. This drawing is to be read in conjunction with the project site plan, landscape plan, and engineering plan.
 3. The tree inventory includes assessment of trees >10cm DBH. The trees have been assessed based on species, size and condition.
 4. The contractor shall check and verify all existing and proposed grading and conditions on the project and immediately report any discrepancies to the consultant before proceeding with any removals.
 5. The contractor is to be aware of all existing and proposed services and utilities. The contractor is responsible for having all underground services and utility lines staked by each agency having jurisdiction prior to commencing work.
 6. This drawing is to be used for development approval only.
 7. Do not leave any holes open overnight.
 8. Keep area outside construction zone clean and useable by others at all times. Contractor shall thoroughly clean areas surrounding the construction zone at the end of each work day.
 9. Contractor to make good any and all damages outside of the development area that may occur as a result of tree removals at no extra cost.
 10. This drawing is Copyright MHBC Planning, 2021.

1 TREE INVENTORY PLAN
Scale 1:200

TREE INVENTORY NOTES

Tree #	Common Name	Botanical Name	DBH (CM)	Condition	Comments	Recommendation
1	Colorado Blue Spruce	Picea pungens	24	F/G		Remove
2	Norway Maple	Acer platanoides	42	P	90% dead; Significant deadwood in canopy	Retain
3	Colorado Blue Spruce	Picea pungens	21	F/D		Remove
4	Colorado Blue Spruce	Picea pungens	18	F/G		Remove
5	Manitoba Maple	Acer negundo	72	F	Moderate to significant deadwood in canopy	Remove
6	Linden sp.	Tilia sp.	65	F	Minor deadwood in canopy	Remove
7	Linden sp.	Tilia sp.	95	F	Moderate to significant deadwood in canopy; Crown has significant dieback	Remove
8	Little Leaf Linden	Tilia cordata	21	F	Signs of Gypsy moth	Remove
9	Little Leaf Linden	Tilia cordata	25	F	Base of trunk is leaning; Signs of Gypsy moth	Remove
10	Little Leaf Linden	Tilia cordata	24	F	Signs of Gypsy moth	Remove
11	Little Leaf Linden	Tilia cordata	25	F	Signs of Gypsy moth	Remove
12	Little Leaf Linden	Tilia cordata	24	F	Signs of Gypsy moth	Remove
13	Black Walnut	Juglans nigra	20	F	Moderate lean	Remove
14	Norway Maple	Acer platanoides	19	F		Remove
15	Manitoba Maple	Acer negundo	21	F		Remove
16	Manitoba Maple	Acer negundo	21	F		Remove
17	Manitoba Maple	Acer negundo	73	F	Tree is leaning over adjacent tree	Remove
18	Elm sp.	Ulmus sp.	53.62	F	Co-dominant stems; Growing out of porch; signs of gypsy moth	Remove
19	Apple sp.	Malus sp.	18	F/P	Deadwood; signs of urban stress	Remove
20	Manitoba Maple	Acer negundo	35	F	Tree is located on development property and is leaning west towards development	Remove
21	Manitoba Maple	Acer negundo	27	F	Tree is located on development property and is leaning west towards development	Remove
22	Norway Maple	Acer platanoides	22	F	Tree is located on development property and is not leaning	Remove
23	Cedar sp.	Thuja sp.	25	F/P		Remove
24	Cedar sp.	Thuja sp.	19	F/P		Remove
25	Cedar sp.	Thuja sp.	26	F/P		Remove
26	Cedar sp.	Thuja sp.	28	F/P		Remove
27	Manitoba Maple	Acer negundo	35	F		Remove
28	Manitoba Maple	Acer negundo	28	F		Remove
29	Manitoba Maple	Acer negundo	99	F	Moderate to significant deadwood in canopy	Remove
30	Norway Maple	Acer platanoides	19	F		Remove
31	Maple sp.	Acer sp.	23	F/P	Showing significant signs of stress	Remove
32	Red Maple	Acer rubra	83	F	Significant deadwood in canopy; Signs of rot; Grown into fence line	Retain
33	Maple sp.	Acer sp.	11	D		Tree has been previously removed
34	Silver Maple	Acer saccharinum	13	P/D	Tree is in decline	Remove
35	Norway Maple	Acer platanoides	23	F		Remove
36	Norway Maple	Acer platanoides	29	F		Remove
37	Norway Maple	Acer platanoides	20	P	Significant damage to trunk; Significant deadwood	Remove
38	Manitoba Maple	Acer negundo	13	F		Tree has been previously removed
39	Silver Maple	Acer saccharinum	-	P/D	In decline; crown 90% dead; signs of gypsy moth	Remove

2 CITY OF BARRIE TREE PROTECTION DETAILS
n.t.s

REVISION NO.	DATE	ISSUED / REVISION	BY
6	NOVEMBER 05, 2021	ISSUED FOR SPA	CC
5	JUNE 22, 2021	ISSUED FOR SPA	CC
4	APRIL 10, 2018	ISSUED FOR REVIEW	SN
3	DECEMBER 04, 2017	ISSUED FOR REVIEW	SN
2	NOVEMBER 24, 2017	ISSUED FOR REVIEW	LK

**PLANNING
URBAN DESIGN
& LANDSCAPE
ARCHITECTURE**

230-7050 WESTON ROAD WOODBRIDGE, ON, L4L 6G7 | P: 905 761 5388 F: 905 761 5389 | WWW.MHBCPLAN.COM

STAMP		DATE	JUNE 2021
		DRAWN BY	NV
		PLAN SCALE	1:200
		FILE NO.	2011C
		CHECKED BY	N.M.
		CITY REF. #	D11-016-2021
PROJECT	67 OWEN STREET BARRIE, ONTARIO		
OWNER	THE RESIDENCES ON OWEN LTD.		
FILE NAME	TREE INVENTORY, PROTECTION, AND REMOVALS	DWG NO.	TI-1

