

157 ARDAGH ROAD RESIDENTIAL DEVELOPMENT

TREE INVENTORY, ANALYSIS, AND PRESERVATION PLAN



157 ARDAGH ROAD

CITY OF BARRIE, ONTARIO, COUNTY OF SIMCOE

DECMEBER 2021

OUR FILE: LA 590-21

MUNICIPAL FILE: D28-058-2021

PREPARED BY:



LANDSCAPE ARCHITECTURE & CONSULTING ARBORISTS

606-55 CEDAR POINTE DRIVE,

BARRIE, ONTARIO L4N 5R7

TELEPHONE: 705-796-1122

Email: info@LEGroupLtd.com Website: www.LEGroupLtd.com

© Landmark Environmental Group Ltd, 2021

TABLE OF CONTENTS

Table of Contents.....	2
1.0 Scope/Assignment.....	3
2.0 Proposed Development.....	3
3.0 Method	4
4.0 Observations.....	5
5.0 Study Criteria.....	6
6.0 Analysis and Recommendations.....	6
6.1 Summary/Recommendations.....	7
7.0 Arborist Declaration.....	8
8.0 Glossary of Arboricultural Terms.....	9

FIGURES

Figure 1 Airphoto of Subject Site and Surrounding Area.....	4
---	---

TABLES

Table 1 List of Observed Woody Plant Species on the Subject Site.....	5
---	---

APPENDICES

Appendix A: Conceptual Site Plan	10
Appendix B: Tree Inventory & Preservation + Details	11-14
Appendix C: Tree Inventory and Assessment Table.....	15-16
Appendix D: Selected Site Photos.....	17

1.0 Scope/Assignment:

The Landmark Environmental Group Ltd. (LEGGroup) (Jim Hosick, OALA, ISA Arborist # 1098A) is retained by Mr. Michael Lato (hereafter referred to as the Applicant) to provide Consulting Arboriculture services to lands generally west of Highway 400 and north of Essa Road in the City of Barrie, municipally known as 157 Ardagh Road. The assignment is to prepare a Tree Inventory, Analysis, and Preservation Plan in support of a residential redevelopment. LEGGroup is requested to create a tree inventory, assessment and preservation plan report to assess the existing trees on the subject site, indicate those trees that can be preserved and the methods for protecting the same. Further, those trees that cannot be preserved either by poor or declining health, structural deficiencies or to facilitate the proposed development on the site, are indicated to be removed. Any trees that are removed to facilitate the new development is to be preserved in accordance with City of Barrie Tree Protection policies.

Specifically, LEG was assigned to provide the following services:

- Review site data including survey, and engineering plans, to provide for a site visit and correspond with City staff (File: D28-058-2021) and the Lake Simcoe Region Conservation Authority (LSRCA) as applicable;
- Conduct a field review to inventory tree specimens, tree groupings, boundary trees visually assessing and identifying the type, location, size and quality of any trees on site within the developable area and indicating the presence of any Butternut (in accordance with the *Endangered Species Act 2007*);
- Provide a Tree Inventory, Analysis and Preservation Report that sets out the methodology, observations, criteria, analysis and conclusions of our review and area conditions;
- Indicate on a Tree Inventory and Protection Plan, those trees that are suitable for preservation or removal and providing the methods of protecting the same;

It is the intent in the undertaking of this Report, to comply with the City of Barrie Tree Preservation policies and any requirements of the Lake Simcoe Region Conservation Authority.

2.0 Proposed Development:

The subject site is located on the south side of Ardagh Road, east of Ferndale Drive South and legally described as Lot 12, Registered Plan 914 in the City of Barrie, Ontario (see **Survey in Appendix A**) The Owners are proposing to sever the site into two approximately equal lots along the entire length of the property where there is currently only an accessory building on the lot.

The limits of the Arborist study were confined to the subject property limits of the proposed development.

This Tree Inventory, Analysis & Preservation Report is submitted in support of and intended to accompany those documents submitted to the City of Barrie for their approval for the development of the site.

Below, is an air photo illustrating the location of the subject site (red lines show the site boundaries):



Figure 1: Airphoto of Subject Site (Boundary Highlighted) and Surrounding Area (courtesy Simcoe County GIS)

3.0 Method:

A summary of the inventory, observations and assessments that were determined in the field can be found in **Appendix C** at the end of this Report.

The tree assessments were identified in accordance with the detailed typical criteria used in best arboricultural practices to indicate the merits of tree preservation including the species (*Latin* and common names), size diameter at breast height (DBH), maturity, biological health, structural concerns (if any), condition rating and recommendations for preservation or removal of existing specimen trees.

Condition ratings applied to overall tree assessments using the above-noted criteria range from 1 (poor) to 5 (excellent). Typically, those trees being assessed a condition rating of 1-3 are recommended for removal while those trees being assessed a condition rating of 4-5 are recommended for preservation unless there are extenuating circumstances regarding the development of the site. The criterion is also applied to assist in assessment of their potential for survival in-situ post construction.

For the purposes of this Report, only those trees over 10cm DBH were captured. No shrubs or low understory perennials were captured in the data.

Each on-site/boundary tree was assigned a key number (Tree Nos. 1-69) and offsite trees assigned a key letter (A-B) and observations relating to each tree were tabulated in the Tree Inventory (**Appendix C**). LEGroup staff provided tree locations and data to coincide with current City of Barrie Tree Protection policies. Each tree is located on a Tree Inventory and Preservation Map corresponding to the number assigned and can be seen in the Tree Inventory, Assessment and Preservation Plan (**EX-1**) as shown in **Appendix B**.

4.0 Observations

On October 6th 2021, B. Bell (Consulting Arborist; BScF & Forestry Technician) and L. Orlovski (Consulting Arbor Assistant) visited the subject site with the intent to review the trees to create an inventory/assessment of the individual tree specimens present within the proposed development at 157 Ardagh Road, Barrie. LEGroup staff also made a cursory review of existing trees exterior to the subject property to visually assess the quality of the vegetation.

LEGroup staff observed sixty-nine (69) trees at a DBH greater than 10cm on the subject site (Tree Nos. 1-69) of those, five (7) potential boundary trees were recorded. LEGroup also reviewed two (2) offsite trees and one (1) boundary hedge. All trees and woody plant material can be seen in the **Tree Inventory and Assessment Table (Appendix C)**.

LEGroup staff noted that the site has slope toward Ardagh Road with a northerly aspect.

The following woody plant species were observed on the subject site during fieldwork that gives an indication of the species make-up of the site:

Latin Name	Common Name	% Of Total Species
<i>Acer negundo</i>	Manitoba Maple	7.4%
<i>Acer saccharum</i>	Sugar Maple	1.5%
<i>Betula papyrifera</i>	Paper Birch	1.5%
<i>Fraxinus pennsylvanica</i>	Green Ash	4.4%
<i>Juglans nigra</i>	Black Walnut	1.5%
<i>Pinus resinosa</i>	Red Pine	5.9%
<i>Pinus sylvestris</i>	Scots/Scotch Pine	35.3%
<i>Populus tremuloides</i>	Trembling Aspen	7.4%
<i>Prunus serotina</i>	Black Cherry	5.9%
<i>Quercus rubra</i>	Red Oak	1.5%
<i>Tilia americana</i>	Basswood	25.0%
<i>Ulmus pumila</i>	Siberian Elm	1.5%
<i>Ulmus rubra</i>	Red or Slippery Elm	1.5%
Total (Subject to Rounding)		100.0%

Table 1 List of Observed Woody Plant Species on the Subject Site

As shown in **Table 1** above, the most frequently encountered tree species in the site inventory is Scots Pine at 35%.3, followed by Basswood (25%), Manitoba Maple (7.4%), Trembling Aspen (7.4%), Red Pine (5.9%), Black Cherry (5.9%), Green Ash (4.4%), Sugar Maple (1.5%), White Birch (1.5%), Black Walnut (1.5%), Red Oak (1.5%), Siberian Elm (1.5%) and Red Elm (1.5%).

Staff observed that the Scots Pine on the site (Trees Nos. 18, 20, 31, 33-41, 51-54, 56-58, 60-63) have lower branch dieback, one-sided branching, twisted trunks and small live crowns typical of trees in forested conditions (**see Photo B, Appendix D**). Staff also noted significant needle drop and bark beetles (suspected to be Pine Engraver) causing decline in the Scots and Red Pine on site.

Many of the Basswood (Trees Nos. 4, 6, 9, 13, 14, 16, 21-24, 27-30, 32, 42, 45 & 55) exhibited characteristics found in forest conditions such as lower branch dieback, included (weakened) bark, multiple leaders and cracking/twisted trunks. Such defects were found to be affecting the structural integrity of the trees which is reflected in the assessment given for each tree (**Tree Inventory and Assessment Table, Appendix C**).

LEGroup staff observed Manitoba Maples (Tree Nos. 1, 2, 10, 15) and Black Cherry (12, 43, 50 & 59) in marginal condition and showing characteristics commonly found in wooded areas such as corrected leans, one sided canopies, trunk wounds, offset canopies and dieback (**Photo A, Appendix D**).

The remaining trees observed included Sugar Maples, Paper Birch, Green Ash, Black Walnut, Red Pine Trembling Aspen, Oak and Elm were found scattered throughout the site, noted to be in poor to marginal condition and also exhibited characteristics found in forested conditions as noted above (**see Photos A & B in Appendix D**).

Regarding boundary tree vegetation, LEGroup staff observed eight trees (Tree Nos. 1, 2, 10, 13, 46, 67-69) that are considered boundary trees as they have trunks crossing over the property line. Tree 69 is an Eastern White Cedar hedge located along the east property line with a portion of its canopy found to be crossing the property line (see **TP-1 & TP-2**).

LEGroup staff did not identify any Butternut (*Juglans cinerea*) on the subject parcel during the on-site inventory in accordance with the requirements of the *Endangered Species Act, 2007*.

5.0 Study Criteria

Tree observations were recorded individually, as set out in the Tree Inventory and Assessment Table (**Appendix C**), in accordance with the criteria established by common arboricultural practice including:

- ✓ Latin/Common Name of tree;
- ✓ Size (mm cal);
- ✓ Condition/Comments; and
- ✓ Recommendation for Preservation or Removal

Tree locations are on the Tree Inventory and Preservation Plan were recorded and adjusted however, the locations are approximate as shown on **Drawing ARB-1 in Appendix B**.

6.0 Analysis and Recommendations

The following analysis criteria were generally applied to measure the merits of tree preservation:

- Species (including native & non-native)
- Size/Maturity
- Structure
- Health
- Location
- Areas of proposed development.

These criteria were applied to the tree assessments to determine the extent of preservation and removal. In addition, the criterion is applied to assess of their potential for survival in-situ post construction.

LEGroup staff found the existing trees onsite are in poor to marginal condition with form defects such as significant leans, structural issues and were to be generally in declining health. The Scots and Red Pine are in decline due to insect infestation, and the deciduous trees onsite have poor form causing possible structural concerns as a result of being located in a forested area.

LEGroup recommends the removal of Tree No. 1, 2, 10, 13, (boundary trees) that are in poor condition, possess the potential to fail due to their leans (can be seen by their offset canopy on **TP-1**), and are of limited aesthetic/intrinsic value. Tree No. 46, 68 & 69 (boundary trees) that are in poor to marginal condition are also recommended to be removed due their decline in health from bark beetles, and low intrinsic value.

The applicant has acquired the consent to remove these trees along the east property line from the owner of 153 Ardagh Road. The recommendations for removal noted above can be reviewed in **TP-1 & TP-2, Appendix B**.

LEGroup are of the opinion that Tree No. 67 (*Ulmus pumila*, boundary tree) is in poor condition, and is of limited aesthetic/intrinsic value due to its introduced status. The applicant has acquired the consent to remove this tree along the east property line from the owner of 159 Ardagh Road. The recommendations for removal noted above can be reviewed in **TP-1 & TP-2, Appendix B**.

Therefore, due to the above-noted defects, LEGroup staff recommends a total of sixty-nine (69) trees (Tree Nos. 1-69) to be removed to accommodate the development and to improve the health of the retained City of Barrie delineated wooded area to the south. The two (2) offsite trees (Tree A & B) located along south property line are recommended to be preserved in-situ with tree preservation fencing placed around the dripline of canopy as seen in **TP-1 & TP-2 (Appendix B)**.

6.1 Summary and Recommendations

In summary, as a result of a proposed residential development at 157 Ardagh Road, the City of Barrie requires that the Applicant submit a Tree Inventory, Assessment and Preservation Plan along with their application for a severance, for their review (File: D28-058-2021).

The following is a summary of the recommendations contained in this Report:

- That sixty-nine (69) trees (Tree Nos. 1-69) are recommended for removal and two (2) offsite trees (Tree A & B) are recommended to be preserved on the subject site in accordance with the findings of this Report;
- Provide tree preservation fencing at the dripline of offsite trees (Tree A & B) which represents the tree preservation zone (refer to **TP-1 & TP-2, Appendix B**).
- Removal of Trees should occur outside of breeding bird season (April 1 – August 30), if not possible, consultation with an ecologist to provide a nesting survey is required 48 hours prior to clearing (*Migratory Birds Convention Act, 1994*);
- That trees to be preserved are monitored during and post-construction to ensure continued health;
- No equipment storage or refueling is to take place within the tree preservation zone as established by the preservation fencing;
- Tree preservation fencing is to be removed only after construction on the site is complete and all equipment removed;
- Existing tree branching that interferes with the development works may be lightly pruned by qualified personnel;
- For other preservation methods, please refer to the Tree Preservation Notes on drawing LD-1 in Appendix B.

7.0 Arborist's Declaration

It is the policy of Landmark Environmental Group Ltd. to attach the following clause regarding the limitations:

The Consulting Arborist's visual assessment and recommendations, made in this Report, have been completed based on accepted arboricultural practices and represents a fair and accurate assessment of the number, type, size and condition of trees on the subject property. Such visual assessments of all tree components could include scars, bark damage, external decay, insect infestations, discoloured foliage, crown dieback, an excessive degree of lean from the vertical and above-ground root defects. In addition, environmental conditions, which could affect overall health of the trees such as damaging maintenance practices, have also been taken into consideration where appropriate. However, no tree was dissected, cored or rooting systems assessed through excavation.

We hereby certify that we, Brock Bell and Lauren Orlovski have:

- Conducted the visual inspection of the trees and property referred to in this letter report and have stated my findings accurately in accordance with accepted arboricultural practices without personal interest or bias;
- No current or prospective interest in the property that is the subject of this Report and have no personal interest or bias with respect to the parties involved;
- That our analysis, opinions and conclusions stated our own and based on commonly accepted arboricultural practices;
- That our compensation is not contingent on the reporting of a predetermined conclusion that favours the client; and
- That we are members in good standing with the International Society of Arboriculture (ISA).

We trust the above-noted recommendations are of assistance. If there are any questions regarding the 157 Ardagh Tree Inventory, Analysis, Preservation Report please do not hesitate to contact our Firm at (705) 796-1122.

Prepared by,



Brock Bell BScF
Consulting Arborist/Forest Technician
Landmark Environmental Group Ltd.




Lauren Orlovski
Consulting Arbor Assistant
Landmark Environmental Group Ltd.

Reviewed by,



Jim Hosick, OALA, RPP
Landscape Architect-Principal,
ISA Certified Arborist No. 1098-A
ArborCanada Qualified Appraiser #2164
Member, American Society of Consulting Arborists
Landmark Environmental Group Ltd.



8.0 Glossary of Arboricultural Terms

Arboriculture – practice and study of the care of trees and other woody plants in the landscape.

Bark Whitening – Bark of tree is flaking revealing lighter color underneath. Common in Ash trees and is usually a symptom caused by raptors foraging for bugs.

Beech Bark Disease – Fungal infection of beech trees often leads to mortality. Caused by the Beech Scale insect

Branch – stem arising from a larger stem. A subdominant stem.

Canopy – collective branches and foliage of a tree or a group of trees' crowns.

Canopy sweeping – Form of the tree is concave from the base of the tree to the top.

Co-dominant branches/stems (dual Leaders)– forked branches nearly the same size in diameter, arising from a common junction and lacking a normal branch union.

Crown – upper part of the tree, measured from the lowest branch, including all the branches and foliage.

DBH – acronym for tree diameter at breast height. Measured 1.4 meters above ground.

Dieback – condition in which the branches in the tree crown die from the tips toward the centre.

Drip-line – imaginary line defined by the branch spread of a single plant or group of plants.

Epicormic Branching – Shoot(s) arising from a latent or adventitious bud (growth point), often a sign of stress in tree.

Included Bark – bark that becomes embedded in a crotch (union) between branch and trunk or between codominant stems. Causes a weak structure.

Interior Decay – Moisture or fungus that has entered a wound in a tree and has begun to rot away the internal, structural wood.

Leader – primary terminal shoot or trunk of a tree. Large, usually upright stem. A stem that dominates a portion of the crown by suppressing lateral branches.

Pine Shoot - It's the shoot of a new branch coming out, and there are no needles visible yet.

Pruning – removing branches from a tree or other plants to achieve a specified objective.


Root Ball - The largest density of roots located underneath trunk of tree.


Elevated Root Plate – Roots at the base of the tree are elevated and don't match existing grade.

Root Suckering – Roots of a tree sprouting new growth creating new stems feeding on the original root system, often a sign of stress in tree.

Tree Protection Zone (TPZ) – Defined area within which certain activities are prohibited or restricted to prevent or minimize potential injury to designated trees, especially during construction or development

Appendix A: Conceptual Site Plan



[illegible]


Tree Preservation Plan 1 (TP-1)



Tree Preservation Plan 2 (TP-2)



Tree Preservation Details (LD-1)

KEY PLAN				DATE	BY	NO.
GENERAL NOTES 1. The project is located at the intersection of Highway 1 and Highway 26, in the City of Barrie. 2. The project consists of a new building and parking lot. 3. The building is to be constructed of brick and concrete. 4. The parking lot is to be constructed of asphalt. 5. The project is to be completed within 12 months. 6. The project is to be completed within the budget of \$1,000,000. 7. The project is to be completed within the scope of the contract. 8. The project is to be completed within the time frame of the contract. 9. The project is to be completed within the quality standards of the contract. 10. The project is to be completed within the safety standards of the contract.						
STAMP <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="border: 1px solid black; padding: 5px;"> APPROVAL CITY OF BARRIE 1986 (Seal) </div> <div style="border: 1px solid black; padding: 5px;"> APPROVAL MR. MICHAEL LATO 157 ARDAGH ROAD, BARRIE, ON (Seal) </div> </div>						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS OFFICE: 705-796-1122 1000 Highway 10 West Windsor, Ontario N9A 6K6 TEL: 705-796-1122 FAX: 705-796-1123 WWW.LANDMARK-ARCHITECTS.COM						
LANDMARK ARCHITECTS & CONSULTING ARCHITECTS						

[illegible]

APPROVED	DATE: JUNE 2016	PROJECT NAME: BRIDGE IMPROVEMENT
REVIEW:	SCALE: N.T.S.	
1	1	

NOTES:

1. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
2. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
3. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
4. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
5. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
6. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
7. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
8. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
9. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.
10. BROWN TAPE TO BE REMOVED IMMEDIATELY UPON INSTALLATION.

[illegible]

Appendix C: Tree Inventory and Assessment Table

ONSITE TREE INVENTORY						
Key	Latin Name	Common Name	Tree DIA (cm dbh)	Notes	Assessment	Canopy Radius (m)
1	<i>Acer negundo</i>	Manitoba Maple	39.6	lean toward west, interior decay, epicormic branching, poor form, boundary tree	1 Poor	9.1
2	<i>Acer negundo</i>	Manitoba Maple	27.3	lean, epicormic branching, multiple leaders, included bark, pruning, large white face scar, boundary tree	1 Poor	7.4
3	<i>Ulmus rubra</i>	Red or Slippery Elm	14.3	canopy dieback, defoliation, one sided canopy	2 Marginal	3.5
4	<i>Tilia americana</i>	Basswood	18.4	lower branch dieback	2 Marginal	1.5
5	<i>Fraxinus pennsylvanica</i>	Green Ash	12.8	dual leader, defoliated	2 Marginal	1.0
6	<i>Tilia americana</i>	Basswood	13.9	Included bark	2 Marginal	1.2
7	<i>Betula papyrifera</i>	Paper Birch	19.9, 10.2	exposed root flares, one sided canopy, connected to adjacent tree	2 Marginal	4.2
8	<i>Populus tremuloides</i>	Trembling Aspen	29.1	connected to adjacent tree	2 Marginal	3.0
9	<i>Tilia americana</i>	Basswood	14	lower branch dieback	2 Marginal	1.0
10	<i>Acer negundo</i>	Manitoba Maple	10.8	lean toward Northeast, epicormic branching, dead branches, abnormal flare, lower branch dieback, boundary tree	1 Poor	5.5
11	<i>Quercus rubra</i>	Red Oak	23.8	winding trunk	2 Marginal	4.0
12	<i>Prunus serotina</i>	Black Cherry	16.7	canopy dieback, defoliated	2 Marginal	1.2
13	<i>Acer negundo</i>	Manitoba Maple	21.5, 22	multiple trunks, significant lean, deadwood, sweeping trunk, included bark, multiple leaders, boundary tree	2 Marginal	5.5
14	<i>Tilia americana</i>	Basswood	13.7, 16.8, 10.6	multiple leaders, lower branch dieback, included bark	2 Marginal	1.7
15	<i>Acer negundo</i>	Manitoba Maple	21.2, 21.3, 10.6	multiple leaders, significant corrected lean, unstable endweight, defoliated	2 Marginal	3.0
16	<i>Tilia americana</i>	Basswood	10.5	lower branch dieback	2 Marginal	0.5
17	<i>Pinus sylvestris</i>	Scots/Scotch Pine	14.8	significant defoliation, lower branch dieback	1 Poor	0.7
18	<i>Pinus sylvestris</i>	Scots/Scotch Pine	13.9	significant defoliation, lower branch dieback, uncompartimentalized wound	1 Poor	0.8
19	<i>Fraxinus pennsylvanica</i>	Green Ash	23.8	basal trunk wound, uncompartimentalized wound, dual leader	2 Marginal	2.5
20	<i>Pinus sylvestris</i>	Scots/Scotch Pine	23.2	lower branch dieback	1 Poor	2.3
21	<i>Tilia americana</i>	Basswood	29.9	multiple leaders	2 Marginal	3.5
22	<i>Tilia americana</i>	Basswood	31.6	one sided branching, one sided canopy	2 Marginal	4.0
23	<i>Tilia americana</i>	Basswood	17.4, 15.6	dual leaders, lower branch dieback	2 Marginal	5.0
24	<i>Tilia americana</i>	Basswood	10.6	dual leader, minor corrected lean	2 Marginal	1.0
25	<i>Juglans nigra</i>	Black Walnut	10.2	corrected lean, multiple leaders, significant defoliation, lower branch dieback	1 Poor	2.5
26	<i>Acer saccharum</i>	Sugar Maple	13.3	lower branch dieback	2 Marginal	1.7
27	<i>Tilia americana</i>	Basswood	16.2	lower branch dieback, trunk gall	2 Marginal	2.1
28	<i>Tilia americana</i>	Basswood	9.2, 10.8, 6.2, 7.5	multiple leaders, included bark, one sided canopy	2 Marginal	4.5
29	<i>Tilia americana</i>	Basswood	10.7	frost crack, winding trunk	2 Marginal	2.8
30	<i>Tilia americana</i>	Basswood	12.4	exposed root flares, dual leaders, winding trunk	2 Marginal	3.5

BOUNDARY TREE

Key	Latin Name	Common Name	Tree DIA (cm dbh)	Notes	Assessment	Canopy Radius (m)	Preserve/Remove
31	<i>Pinus sylvestris</i>	Scots/Scotch Pine	24.1	significant defoliation, lower branch dieback, canopy dieback, uncompartimentalized wound	1 Poor	2.5	Remove
32	<i>Tilia americana</i>	Basswood	18.3	lower branch dieback, winding trunk	2 Marginal	2.5	Remove
33	<i>Pinus sylvestris</i>	Scots/Scotch Pine	13.6	significant defoliation, lower branch dieback	1 Poor	1.0	Remove
34	<i>Pinus sylvestris</i>	Scots/Scotch Pine	20.8	lower branch dieback, significant defoliation	1 Poor	1.2	Remove
35	<i>Pinus sylvestris</i>	Scots/Scotch Pine	18.6	lower branch dieback, significant defoliation	1 Poor	1.5	Remove
36	<i>Pinus sylvestris</i>	Scots/Scotch Pine	12.5	significant defoliation, one sided branching, lower branch dieback	1 Poor	0.5	Remove
37	<i>Pinus sylvestris</i>	Scots/Scotch Pine	21.6	significant defoliation, lower branch dieback	1 Poor	1.3	Remove
38	<i>Pinus sylvestris</i>	Scots/Scotch Pine	13.9	significant defoliation, lower branch dieback	1 Poor	0.7	Remove
39	<i>Pinus sylvestris</i>	Scots/Scotch Pine	14.1	dual leader, significant defoliation, lower branch dieback	1 Poor	0.5	Remove
40	<i>Pinus sylvestris</i>	Scots/Scotch Pine	20.4	pruning, uncompartimentalized wound, lower branch dieback, defoliation	1 Poor	1.5	Remove
41	<i>Pinus sylvestris</i>	Scots/Scotch Pine	13.5	significant defoliation, lower branch dieback, winding trunk	1 Poor	1.0	Remove
42	<i>Tilia americana</i>	Basswood	16.2	winding trunk	2 Marginal	2.0	Remove
43	<i>Prunus serotina</i>	Black Cherry	11.3	lower branch dieback, included bark, minor corrected lean	2 Marginal	3.0	Remove
44	<i>Populus tremuloides</i>	Trembling Aspen	20.4	minor corrected lean, winding trunk, lower branch dieback	2 Marginal	5.5	Remove
45	<i>Tilia americana</i>	Basswood	16.7	uncompartimentalized wound	2 Marginal	3.8	Remove
46	<i>Pinus resinosa</i>	Red Pine	39.6	barl beetle, lower branch dieback, dead branches, one sided branching to north, boundary tree	2 Marginal	3.7	Remove
47	<i>Fraxinus pennsylvanica</i>	Green Ash	13.9, 9.8	dual leader, included bark	2 Marginal	4.0	Remove
48	<i>Pinus resinosa</i>	Red Pine	32.5	trunk gall, uncompartimentalized wound, pruning, lower branch dieback	2 Marginal	3.7	Remove
49	<i>Pinus resinosa</i>	Red Pine	24.1	lower branch dieback	2 Marginal	2.5	Remove
50	<i>Prunus serotina</i>	Black Cherry	24.8	significant corrected lean, unstable endweight, dual leader	2 Marginal	6.0	Remove
51	<i>Pinus sylvestris</i>	Scots/Scotch Pine	18.8	significant defoliation, lower branch dieback, canopy dieback	1 Poor	1.2	Remove
52	<i>Pinus sylvestris</i>	Scots/Scotch Pine	10.4	significant defoliation, lower branch dieback, canopy dieback	1 Poor	0.5	Remove
53	<i>Pinus sylvestris</i>	Scots/Scotch Pine	14.7	brown needles, defoliation, lower branch dieback	1 Poor	1.0	Remove
54	<i>Pinus sylvestris</i>	Scots/Scotch Pine	20.4	lower branch dieback, defoliation	1 Poor	2.5	Remove
55	<i>Tilia americana</i>	Basswood	26.1	bulging trunk	2 Marginal	2.3	Remove
56	<i>Pinus sylvestris</i>	Scots/Scotch Pine	13.3	one sided canopy, lower branch dieback, defoliation	1 Poor	1.5	Remove
57	<i>Pinus sylvestris</i>	Scots/Scotch Pine	15.4	significant defoliation, canopy dieback, lower branch dieback	1 Poor	0.5	Remove
58	<i>Pinus sylvestris</i>	Scots/Scotch Pine	14.3	lower branch dieback	1 Poor	1.1	Remove
59	<i>Prunus serotina</i>	Black Cherry	13.8	corrected lean, one sided canopy	2 Marginal	2.0	Remove
60	<i>Pinus sylvestris</i>	Scots/Scotch Pine	15.7	lower branch dieback, one sided canopy	1 Poor	1.7	Remove
61	<i>Pinus sylvestris</i>	Scots/Scotch Pine	17.5	lower branch dieback, winding trunk, one sided canopy	1 Poor	1.8	Remove
62	<i>Pinus sylvestris</i>	Scots/Scotch Pine	24.6	one sided branching, lower branch dieback, minor corrected lean	1 Poor	2.3	Remove
63	<i>Pinus sylvestris</i>	Scots/Scotch Pine	11	uncompartimentalized wounds, one sided branching	1 Poor	1.2	Remove
64	<i>Populus tremuloides</i>	Trembling Aspen	21.8	winding trunk, basal bark crack, suspected interior decay	2 Marginal	3.0	Remove
65	<i>Populus tremuloides</i>	Trembling Aspen	10	corrected lean, basal trunk wound, winding trunk	2 Marginal	1.9	Remove
66	<i>Populus tremuloides</i>	Trembling Aspen	13.6	basal trunk wound, corrected lean, frost crack, suspected interior decay, included bark	2 Marginal	1.1	Remove
67	<i>Ulmus pumila</i>	Elm	26, 20.5, 30	multiple trunks, dead branches, one sided branching, lower branch dieback, pruning damage, multiple leaders, included bark, interior decay, boundary tree	1 Poor	5.0	Remove
68	<i>Pinus resinosa</i>	Red Pine	23.8	Onw sided branching, lower branch dieback, bark beetle, boundary tree	2 Marginal	4.0	Remove
69	<i>Thuja occidentalis</i>	Eastern White Cedar	Hedge <5cm DBH	epicormic branching, multiple leaders, thin foliage, competition with adjacent trees, boundary hedge	1 Poor	1.0	Remove

OFFSITE TREE INVENTORY			
Key	Latin Name	Common Name	TPZ
A	<i>Pinus resinosa</i>	Red Pine	2.8
B	<i>Pinus sylvestris</i>	Scots/Scotch Pine	2.8

Appendix D: Selected Site Photos



Photo A: Photo of Manitoba Maple (Tree Nos. 1 & 2) showing significant western lean and unstable end weight.



Photo B: Photo of typical canopy of Scots Pine at the site.