

571 Welham Road, Barrie			Appendix "A" Rev. 2		NFA Normal for Age TPZ - Minimum Tree Protection Zone	
Review with Arborist Report Rev. #2 Oct. 17, 2020, + Tree Protection Removal Plan Appendix "B" Rev. #1 by P & A Urban Forestry Consulting Ltd.						
Date compiled March 5, 2020		Tree Inventory Action Table			Ddwd - deadwood	Page 15 of 18
#	Species	DBH (cm)	TPZ m	Ownership/ Location	Site Observations/Condition. Good- G , Fair-F, Poor-P	Suggestion in relation to Development /TPZ
1	White Cedar, Thuja occidentalis	16 20, 29,24	N/A	SWC of Site, Opp. Concrete Pad, 14m E. Pole near corner	F, ddwd, NFA, low branches	Install Tree Protection Barrier
2	White Cedar, Thuja occidentalis	51	N/A	8m N. of Corner sign, 12m E. Pole near corner	F, hangar, ddwd	Install Tree Protection Barrier
3	Manitoba Maple, Acer negundo	23, 32,42	N/A	8m N. of Corner sign, 17m E. Pole near corner	F/P, Weak crotch, ddwd, low branches	Install Tree Protection Barrier
4	Black Walnut, Juglans nigra	15	N/A	Toe of Slope, E. #3	F, NFA, low branches	Install Tree Protection Barrier
5	White Cedar, Thuja occidentalis	36,42	N/A	Opp. #3, 5m South	P, top missing, ddwd	Install Tree Protection Barrier
6	Black Locust, Robinia pseudoacacia	29	N/A	3m SE #3	F, weak crotch, ddwd	Install Tree Protection Barrier
7	White Cedar, Thuja occidentalis	37	N/A	2m S. #5	F, 1 sided canopy	Install Tree Protection Barrier
8	White Cedar, Thuja occidentalis	32,22	N/A	2m SE #5	F/P, Top missing, 22cm leader	Install Tree Protection Barrier
9	White Cedar, Thuja occidentalis	31	N/A	2m E. #8	Dead	Install Tree Protection Barrier
10	White Cedar, Thuja occidentalis	36,44	N/A	2m NE #9	F, ddwd, NFA, low branches	Install Tree Protection Barrier
11	White Cedar, Thuja occidentalis	44,38	N/A	5m SE #10	P, Split onto #12, 38cm leader dead	Install Tree Protection Barrier
12	White Ash, Fraxinus americana	18	N/A	1m NW #11	P, bent from #11	Install Tree Protection Barrier
13	Trembling Aspen, Populous tremuloides	25	N/A	Toe of slope in poplar grouping	F, low branches, NFA	Install Tree Protection Barrier
14	Trembling Aspen, Populous tremuloides	27	N/A	S. end of grouping, centred, 1m E. #15	F, crowded, ddwd, NFA	Install Tree Protection Barrier
15	Trembling Aspen, Populous tremuloides	20	N/A	15m N. Ditch, 8m SE #13	P, large dead branches	Install Tree Protection Barrier

571 Welham Road, Barrie		Appendix "A" Rev. 2		NFA Normal for Age TPZ - Minimum Tree Protection Zone		
Review with Arborist Report Rev. #2 Oct. 17, 2020, + Tree Protection Removal Plan Appendix "B" Rev. #1 by P & A Urban Forestry Consulting Ltd.						
Date compiled March 5, 2020		Tree Inventory Action Table		Ddwd - deadwood		Page 16 of 18
#	Species	DBH (cm)	TPZ m	Ownership/ Location	Site Observations/Condition. Good- G , Fair-F, Poor-P	Suggestion in relation to Development /TPZ
16	Trembling Aspen, Populous tremuloides	22	N/A	1m E. #14	F, crowded, ddwd, NFA	Install Tree Protection Barrier
17	Trembling Aspen, Populous tremuloides	20	N/A	1m SE #16	F, crowded, ddwd, NFA	Install Tree Protection Barrier
18	Trembling Aspen, Populous tremuloides	22	N/A	2.5m E #16	F, crowded, ddwd, NFA	Install Tree Protection Barrier
19	Trembling Aspen, Populous tremuloides	20	N/A	1/3 up slope	F, crowded, ddwd, NFA	Install Tree Protection Barrier
20	White Pine, Pinus strobus	21	N/A	mid slope	F, low branches, NFA	Install Tree Protection Barrier
21	White Pine, Pinus strobus	27	N/A	0.3m E. #20	F, low branches, NFA	Install Tree Protection Barrier
22	White Ash, Fraxinus americana	20,22	N/A	1m S. top of slope, 5m W of road culvert	Dying	Install Tree Protection Barrier
23	White Ash, Fraxinus americana	23	N/A	N. side driveway, opp culvert	Dying	Install Tree Protection Barrier
24	White Pine, Pinus strobus	20	N/A	7m E. Culvert, 3m NE driveway	F, low branches, NFA	Install Tree Protection Barrier
25	White Cedar, Thuja occidentalis	30	N/A	4m E. Driveway	F, low branches, NFA, stubs	Install Tree Protection Barrier
26	White Cedar, Thuja occidentalis	20	N/A	1m SE #25	F, low branches, NFA	Install Tree Protection Barrier
27	White Pine, Pinus strobus	20	N/A	2m NE #25	F, low branches, NFA	Install Tree Protection Barrier
28	White Cedar, Thuja occidentalis	35,10	N/A	15m S. top of slope, 3m E. Fire hydrant at road	P, Dying top, low branches	Install Tree Protection Barrier
29	Trembling Aspen, Populous tremuloides	20	N/A	2m S. Top of slope	F, crowded, NFA	Install Tree Protection Barrier
30	Black Willow, Salix nigra	Avg. 20 (7)	N/A	Tableland, E. side of site, south tree west of berm	F, Low branches, leader decay	Remove, Construction conflict

571 Welham Road, Barrie			Appendix "A" Rev. 2		NFA Normal for Age TPZ - Minimum Tree Protection Zone	
Review with Arborist Report Rev. #2 Oct. 17, 2020, + Tree Protection Removal Plan Appendix "B" Rev. #1 by P & A Urban Forestry Consulting Ltd.						
Date compiled March 5, 2020		Tree Inventory Action Table		Ddwd - deadwood		Page 17 of 18
#	Species	DBH (cm)	TPZ m	Ownership/ Location	Site Observations/Condition. Good- G , Fair-F, Poor-P	Suggestion in relation to Development /TPZ
31	Black Willow, Salix nigra	30	N/A	1m N. #30	F, Low branches, lean to north NFA	Remove, Construction conflict
32	Black Willow, Salix nigra	Avg.15 (3)	N/A	on berm, 20m N. #31	F, Low branches, NFA	Remove, Construction conflict
33	Black Willow, Salix nigra	25	N/A	adjacent to rock, 3m NW #32	F, Low branches, NFA	Remove, Construction conflict
34	Black Willow, Salix nigra	Avg 20 (5)	N/A	1.5m E. #33	F, Low branches, NFA	Remove, Construction conflict
35	Black Willow, Salix nigra	Avg 20 (3)	N/A	E. side of berm, 2m E. Top of Slope	F, low branches, vine in canopy	Remove, Construction conflict
36	Black Willow, Salix nigra	36	N/A	E. side of berm, 3m SE. #35	F, broken limb, low branches	Install Tree Protection Barrier
37	Manitoba Maple, Acer negundo	25,33, 20,20	N/A	Toe of slope, 3m N. #35	P, broken leader on ground, ddwd	Install Tree Protection Barrier
38	White Ash, Fraxinus americana	Avg 22	N/A	Toe of slope, 25m S. Yard fence	F, multi-leader, low branches, NFA	Outside of Property on CN lands
39	Trembling Aspen, Populous tremuloides	33	N/A	Mid slope, 25m S. Fence	F, Low branches, NFA	Install Tree Protection Barrier
40	Black Locust, Robinia pseudoacacia	24,23, 20,15	N/A	1m SE of Fence on tableland	F/P, Low branches, broken top, ddwd	Remove, Construction conflict